

Stationary Mounting Bracket Change

Mounting brackets changing from fabricated style to cast style

7 March 2011, from Chris Scahill, Product Manager – Transport Equipment

From March 2011, all Holland Fifth Wheel Stationary Mounting Brackets, except for the heavy duty and plate mount “dog bone” style, were changed from fabricated to a cast style (see Fig 1).

Replacement mounting brackets can only be sourced in PAIRS.

Important:

Stationary mounting brackets must be replaced in pairs. Never mix a new cast style bracket with an older fabricated style bracket. Combining a cast style bracket with an older fabricated style bracket may cause damage to the fifth wheel top plate and/or mounting system.


Warning:

Failure to replace stationary mounting brackets in pairs could cause component damage to the top plate and/or mounting system which, if not avoided, may result in death or serious injury.

The plate mount “dog bone” style mounting brackets will remain in the fabricated style and will continue to be sold under their part number until further notice.

New cast style stationary mounting brackets will be used on all current over the highway fifth wheel models (FW35, FW31 and FW17).

Figure 1



OLD FABRICATED STYLE

IMPORTANT: Stationary brackets must be replaced in pairs. Replacement Kits have been created to include both LH & RH new cast style brackets.

NEW CAST STYLE



XA-7821

REPLACE WITH →

RK-X900
RH & LH Brackets



XA-7822

REPLACE WITH →

RK-X800
RH & LH Brackets



XA-7824

REPLACE WITH →

RK-X600
RH & LH Brackets



New Replacement Rubber Up Shock Bush = XB-10605

Note: Replacement mounting brackets can only be sourced in PAIRS.