



Service Bulletin

- Running Gear

Axle nut fastening procedure change

Axle Types:

All 9019 9022 and 9037 axles

Serial Numbers Involved:

All

Action To Be Taken:

Axle nut fastening torque procedure changed to:

Tightening Torque 900Nm. Each Hub unit must be rotated smoothly at least twice, whilst tightening the nut.

Implementation Date:

With immediate effect

Lincoln Dagnall
Product Manager – SAF axles & suspensions
1 November 2005

